

Oil Field Environmental Incident Summary

Incident: 20160825100106 **Date/Time of Notice:** 08/25/2016 10:01

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: WESTGARD 1-28H

Field Name: PARSHALL

Well File #: 17277

Date Incident: 8/24/2016

Time Incident: 10:00

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 89

Sec: 28

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: B&G Oilfield Services Pat Bertagnolli Pat Bertagno
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels	4	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/3/2017

Clean Up Concluded: 8/24/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

A hydrovac used for daylighting the lines was onsite so immediately they started sucking up the fluid and affected soils and remained onsite. NDIC Pipeline Tech Tim McCoy was onsite.

Wastes Disposal Location: B&G will be responsible for the waste disposal and will be sending EOG the waste disposal information.

Agencies Involved:

Updates

Date: 8/25/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 4 barrels of oil were released on the pipeline right of way. This was not contained to a well pad; more follow-up is needed.

Date: 8/29/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:15. 66 degrees F, partly cloudy, northwest wind 10-15 mph. Observed site and took photos. Met with NDIC pipeline inspector who showed me where the release had occurred. It appeared that the impacted soils had been removed. Company contact will forward disposal records to the NDDoH. Release was on the permitted facility. NDIC retains oversight.